Split

Tuesday, 29/07/2008 1:45:31 PM Melanie Fauteux **Process Sheet** : OUTER TUBE **Drawing Name** : CU-DAR001 Dart Helicopters Services Customer Job Number : 40776 Estimate Number : 13498 : PB6743001205 Part Number P.O. Number : B6743001 P.16 **Drawing Number** : 29/07/2008 S.O. No. : This Issue : N/A Project Number Prsht Rev. : NC : B1 : MACHINED PARTS : 11 Type **Drawing Revision** First Issue Material Previous Run : 05/08/2008 **Due Date** Written By Checked & Approved By Comment : Est Rev:A 08-07-24 new issue DD verified by:ec **Additional Product** Job Number: Machine Or Operation: Description: Seq. #: 6061T6 RDTUBE 1.750 X 0.65W 1.0 M6061T6T1750W065 3.7958 f(s)/Unit Total: 18.9788 f(s) Comment: Qty.: 6061T6 RDTUBE 1.750 X 0_65W batch: 17/08.551 BAND SAW 2.0 BAND SAW Comment: SMALL & MEDIUM FAB RESOURCE 1 1- cut to length as per dwg 2-cut a 27 degree angle on one end of tube as per dwg 2- deburr CONVENTIONAL MILLING MACHINE 3.0 MILLING CONV

08.07.2

Comment: CONVENTIONAL MILLING MACHINE

1- drill holes and mill slot as per dwg PB67-43001

2- deburr

INSPECT WORK TO CURRENT STEP

QC5


Comment: INSPECT WORK TO CURRENT STEP

5.0 PB6743001199 Outer Tube End Cap



Comment: Qty.: 1.0000 Each(s)/Unit 5.0000 Each(s) Total:

Outer Tube End Ca





4.0

Dist.			
V.			
			•
		,×	
			• 1

Tuesday, 29/07/2008 1:45:31 PM • Melanie Fauteux

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: OUTER TUBE

Job Number: 40776

Part Number: PB6743001205

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: 1-Weld end cap as per dwg PB67-43001 2-grind end cap flush

1650 08-C

7.0

QC10



Comment: VISUAL INSPECTION OF GROUND WELDS



8.0 Q0



INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

9.0

PACKAGING 1



Comment: PACKAGING RESOURCE #1

Identify and Stock Location: WW PACKAGING RESOURCE #1



10.0

QC21



Comment: FINAL INSPECTION WIO RELEASE

FINAL INSPECTION/W/O RELEASE




20805/08

Job Completion



mf 08-08-01

				with the second	
				(4)	
And the second					
				x1	
					*
					E
	•				
				9	
				is.	





W/O:		WORK OPPER OFFI					
DATE	STEP	WORK ORDER CHAI	NGES	Justinia B	WITE A		-
		PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
							11

Part No: 1867-43001- 205 PAR #: NA Fault Category: Part Fine Large NCR (Yes) No DQA: Date: 08/05/08

NCR:		VORK ORDER NON-CONFORMANCE (NCR)							
DATE	STEP	Description of NC Section A	Initial	Corrective Action Section B				1	
8/07/29	#	operator the Button and on the wany	Chief Eng	Scrap and Destry Action Description Chief Eng Scrap and Destry Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approva QC Inspecto	
0101111	20	R.C. operate orner Humman error	Brunz		8.9.30	8/7/30	hosiwz.	OElesto	
	the state of	Link Link		to be replaced on split up	K				
								-	
IOTE: Date	0 1 111								

fat a l'			
	**		
			7
			*